



SERVICE BULLETIN

AIRCOOLED MOTORS INC.
SYRACUSE 8, NEW YORK

DATE: 12/16/46
Revised 9/21/53

NO. FSB 44

SUBJECT: LOOSE PLUGS IN INLET MANIFOLDS ON 6A8-215-B8F & B9F ENGINES

There have been several instances of loose inlet manifold plugs on Franklin engines in Seabee installations.

In a few instances plugs have been lost and resultant leanness of the mixture has caused misfiring.

Please check all manifold plugs for looseness. These plugs are located at the bottom of the manifold on both left and right hand sides of the engine.

FRANKLIN SERVICE BULLETIN

FRANKLIN SERVICE BULLETIN

FRANKLIN SERVICE BULLETIN