

# SERVICE PARTS AND ACCESSORIES LETTER

STINSON DIVISION  
CONSOLIDATED VULTEE AIRCRAFT CORPORATION  
WAYNE, MICHIGAN

158-21

TO: Distributors and Distributor's Dealers

LETTER NO.: 20

TITLE: Special Radio Equipment

PAGE 1 OF 2 pages

DATE: October 25, 1947

Gentlemen:

This letter cancels and supersedes Parts and Accessories Letter No. 20 dated September 30, 1947.

Tests conducted at the factory have revealed that a "V" antenna will double or triple the range of the Hallicrafters Transmitter as installed in the 1947 and 1948 models. As you know, this antenna is standard equipment on the 1948 model, but we feel certain that the majority of your customers who own 1947 models will wish to make this installation on their planes. With this in mind, we have developed an antenna installation kit which will be available for shipment within thirty days.

This antenna will have the quickly-detachable feature which is a part of the antenna on the 1948 model and the kit will include a new antenna mast inasmuch as a new loading coil is required. The antenna can be installed and the loading coil tuned in approximately two man hours.

This kit bears our part number 108-3032500-800 and has a list price of \$17.00. Your regular parts discount will apply.

Each of the 1948 models is equipped with brackets to accommodate a VHF Transmitter, Marker Beacon Receiver, and Rotatable Loop so that even if this equipment is not installed at the time a plan is produced, the installation can be made in the field without great difficulty.

Field installation kits for this equipment will be available within thirty days and will be priced as follows:

108-3932503 VHF Transmitter Installation Kit	List Price \$105.50
Distributor Price	\$73.85
Distributor Dealer Price	84.40
108-3932501 Marker Beacon Receiver Installation Kit	List Price \$80.00
Distributor Price	\$56.00
Distributor Dealer Price	64.00
108-3932504 Rotatable Loop Installation Kit	List Price \$79.50
Distributor Price	\$55.65
Distributor Dealer Price	63.60

We do not recommend the installation of the Loop, or Marken Beacon Receiver in a 1947 model. Although the installation is possible, the difficulty involved in installing mounting brackets would make the installations prohibitive from a cost standpoint.

Yours very truly,

STINSON DIVISION  
Consolidated Vultee Aircraft Corporation

*George Martin*  
George Martin  
Service Manager