

SERVICE BULLETIN

STINSON DIVISION

CONSOLIDATED VULTEE AIRCRAFT CORPORATION

WAYNE, MICHIGAN

TITLE: Fuel Valve Shaft

BULLETIN NO. 242

MODELS AFFECTED: 108 (Voyager 150) Serial 108-1
through 108-497

PAGE 1 OF 1

DATE October 14, 1946


As a precautionary measure to prevent possible malfunctioning of the fuel valve handle shaft, part number 108-3021103-0, a change in design was incorporated on airplane Serial No. 108-497.

It is recommended that, on airplanes below this serial number, the fuel valve end of the shaft be inspected for tight fit and positive action in changing from one fuel tank to the other.

In those cases where there is any question of positive action of the shaft now on the airplane, a shaft assembly of the new type may be ordered from our Service Department at no charge.

PARTS REQUIRED:

1 108-3021103-0 Shaft Assy.-Fuel Valve



George Martin
Parts and Service Department