

SERVICE PARTS AND ACCESSORIES LETTER

STINSON DIVISION
CONSOLIDATED VULTEE AIRCRAFT CORPORATION
WAYNE, MICHIGAN

158-L

TO: Stinson Distributors

LETTER NO.: 21

TITLE: New Accessories

PAGE 1 OF 1

DATE: November 10, 1947

Gentlemen:

In response to a great many requests from the field we are making available a Radio Cut-Out Relay and Wheel Fenders.

The Radio Cut-Out Relay is a unit designed to automatically interrupt the radio electrical circuit when the engine starter is engaged. As we previously reported, if the radio is "On" when the starter is engaged, the voltage drop often causes damage to the radio vibrator. The installation of this relay, part number 108-3932505, will prevent damage of this type.

This unit can easily be installed in less than one and a half man hours. Price and delivery information follows:

108-3932505	Radio Cut-Out Relay	\$9.50 List
-------------	---------------------	-------------

This unit is subject to regular parts discounts and deliveries will begin approximately thirty days from date of this letter.

Many dealers have indicated a serious need for wheel fenders for Spring and Winter operation. We will have fenders available within thirty days. List and net prices are indicated below:

Wheel Fenders	\$25.50 Each List
Distributor Price	\$16.60 Each
Distributor Dealer Price	\$19.15 Each

Yours very truly,

STINSON DIVISION
Consolidated Vultee Aircraft Corporation

George Martin
George Martin
Service Manager