

SERVICE BULLETIN

STINSON DIVISION
CONSOLIDATED VULTEE AIRCRAFT CORPORATION
WAYNE, MICHIGAN

TITLE Installation of Metal Heel Plates

BULLETIN NO. 231

MODELS AFFECTED: 108 (Voyager 150)
Serial 108-1 through 108-90

PAGE 1 OF 1

DATE March 19, 1946

To ease operation of the rudder pedals and prevent damage to the cabin floor carpet we suggest that metal heel plates be installed in your Voyager 150 as shown on Figure 1.

The subject heel plates have been incorporated into airplanes bearing serial 108-91 and up.

Necessary parts, tabled below, may be secured by contacting our Service Department and advising the serial number of the airplane for which they are required.

PARTS REQUIRED

- 8 - PK88XA-4-10 Screw
- 8 - #4 Washer
- 2 - 108-3091091 Heel Plates




Figure 1

George Martin

Service Department