

SERVICE PARTS AND ACCESSORIES LETTER

STINSON DIVISION
CONSOLIDATED VULTEE AIRCRAFT CORPORATION
WAYNE, MICHIGAN

TO: Distributors, Direct Factory Dealers and
Distributor's Dealers
TITLE: Ambulance Installation.
Stinson Voyager Models 108, 108-1 and 108-2

LETTER NO.: 17

PAGE 1 OF 2

DATE: August 15, 1947

Gentlemen:

We have had a number of requests for approved plans for making an ambulance installation in the Stinson Voyager. We have been unable to perform any development work on this, but are happy to announce that one of our Distributors has designed and secured C.A.A. approval on a kit installation of this type that is now available to you.

Two such installations have been made and results have been totally satisfactory. The sketch on the reverse side of this page illustrates a complete installation. You will note this installation provides, in addition to the regular pilot space, seating capacity for an attendant in the left rear of the cabin. Space for the stretcher is amply provided for on the co-pilot side.

One of the main features of this installation is that it takes but five minutes to convert from a four passenger plane to an ambulance plane.

Your price on this kit is \$185.00 f.o.b. Denver, Colorado, and includes the following:

- Stretcher
- Matress
- Safety Belts
- 4 Lugs (to be welded to the structure)
- Installation and modification instructions, diagram and pictures.

It is estimated that a maximum of three direct labor hours will be consumed in modifying the airplane for this ambulance installation. This kit has been designed and is available to you through

Mountain States Aviation, Inc.
Comb's Air Park
3800 Dahlia Street
Denver, Colorado

PLEASE PLACE ORDERS DIRECT WITH MOUNTAIN STATES AS STINSON WILL NOT STOCK OR SHIP THIS MATERIAL.

Yours very truly,

STINSON DIVISION
Consolidated Vultee Aircraft Corporation

George Martin

George Martin
Service Manager

GM:LJA

STINSON DIVISION

Consolidated Vehicle Aircraft Division
WAVE, INCORPORATED

August 15, 1947

Dear Sirs:

Reference is made to your letter of August 14, 1947.

Enclosed for you are two copies of the Stinson Voyager Model 108, 108-1 and 108-2

Installation of this type seat is now available to you.

Gentlemen:

We have had a number of requests for approved plans for making an cabin
seats installation in the Stinson Voyager. We have been unable to get
your development work on this, but we hope to announce that one
of our Distributors has designed and secured O.A.A. approval of a
modification of this type seat is now available to you.

Two such installations have been made and results have been excellent.
The sketch on the reverse side of this page illustrates
a complete installation. In addition to the sketch for an attendant
in the lower left corner of the sketch is empty space



Stinson Voyager Model 108, 108-1 and 108-2
Installation of this type seat is now available to you.

Yours very truly,
George Martin
Service Manager

STINSON DIVISION
Consolidated Vehicle Aircraft Division

WAVE, INCORPORATED
3802 Santa Fe Street
Denver, Colorado